

Assunto: **Cancelas - CDSA**
De: José Neto <dsp@docasdesantana.com.br>
Para: CPL <cpl@docasdesantana.com.br>
Data: 17/06/2026 11:47



- WhatsApp Video 2026-06-16 at 14.08.23.mp4 (~1.3 MB)
- WhatsApp Image 2026-06-16 at 14.07.57.jpeg (~185 KB)
- WhatsApp Image 2026-06-16 at 14.07.48.jpeg (~191 KB)
- WhatsApp Image 2026-06-17 at 07.09.09.jpeg (~276 KB)
- WhatsApp Image 2026-06-17 at 07.08.54.jpeg (~230 KB)
- WhatsApp Image 2026-06-17 at 07.08.44.jpeg (~257 KB)
- WhatsApp Image 2026-06-17 at 07.08.43 (2).jpeg (~228 KB)
- WhatsApp Image 2026-06-17 at 07.08.43 (1).jpeg (~266 KB)
- WhatsApp Image 2026-06-17 at 07.08.43.jpeg (~329 KB)

Prezado, bom dia.

Cumpra informar que os postos indicados (g1 e g6) já possuíam cancelas instaladas anteriormente, conforme evidenciado pelos registros fotográficos disponíveis. Nesse sentido, entende-se pertinente avaliar a necessidade de instalação de dispositivos de proteção para os equipamentos, de modo a minimizar riscos de avarias e aumentar sua vida útil operacional.

José Neto
Chefe da Divisão de Segurança Portuária
Supervisor de Segurança
(96) 99120 8625



WhatsApp Image 2026-06-16 at 14.07.57.jpeg
~185 KB



WhatsApp Image 2026-06-16 at 14.07.48.jpeg
~191 KB



WhatsApp Image 2026-06-17 at 07.09.09.jpeg
~276 KB

WhatsApp Image 2026-06-17 at 07.08.54.jpeg
~230 KB



WhatsApp Image 2026-06-17 at 07.08.44.jpeg
~257 KB



WhatsApp Image 2026-06-17 at 07.08.43 (2).jpeg
~228 KB



WhatsApp Image 2026-06-17 at 07.08.43 (1).jpeg
~266 KB



WhatsApp Image 2026-06-17 at 07.08.43.jpeg
~329 KB